

FIG. 5
(PRIOR ART)




FIG. 6




FIG. 7





FIG. 7A



3/4




FIG. 8
(PRIOR ART)




FIG. 9




FIG. 10




FIG. 11




FIG. 13

INPUT QUADRANT(S)	ROTATION OPERATION	OUTPUT QUADRANT(S)
0	-64	3
1	-64	0
0 AND 1	-64	0 AND 3
2	+64	3
1 AND 2	+128	0 AND 3
3	+64	0
2 AND 3	+64	0 AND 3
0 AND 3	NONE	0 AND 3

FIG. 12